

Release notes BL12x v2.02

2025-01-15

What's New

- Fixed issue where flow rate was reset to default (2.2 l/h) after power cycle when 0.5 l/h flow rate was used